

SCS ENGINEERS

February 17, 2016
File No. 25211357.31

Mr. John Terrell
Indianapolis Power & Light
Eagle Valley Generating Station
4040 Bluff Road
Martinsville, IN 46151-7887

Subject: 2015-2 Dike Inspection - Eagle Valley Generating Station
Ponds A, B, and C

Dear Mr. Terrell:

SCS Engineers (SCS) is pleased to submit this dike and basin inspection report for the Indianapolis Power & Light Company (IPL) Eagle Valley Generating Station Ash Ponds A, B, and C. This report was prepared by Mr. David M. Hendron, PE. The report presents a Summary of Visual Observations, and Conclusions and Recommendations. The inspection was performed on November 10, 2015, by Mr. Hendron and Mr. John Terrell. A presentation of the preliminary findings was given to Mr. Terrell at the conclusion of the inspection. A brief summary of the findings was prepared and presented at the meeting after the completion of the field inspection. The weather at the time of this inspection was clear and cool.

For this inspection, we filled out the IPL Dike Field Review Checklist form to document the results of the inspection. The completed form is given in **Attachment A** to this letter report. Documentation of the visual conditions of the dikes and ponds during this inspection is presented in the text of this report and shown in the photographs taken during the inspection. Photographs taken during this inspection are shown in **Attachment B**.

SUMMARY OF VISUAL OBSERVATIONS

IPL's Eagle Valley Plant continues to be operated on an intermittent basis. In general, conditions at the ash ponds continue to appear satisfactory. Water levels in Ash Ponds A, B, and C were below the invert of discharge structures for each pond.

There were no visual indications of seepage flow occurring anywhere on the downstream slope of any of the ponds. The vegetation on the downstream slopes of all the ash ponds was in good condition. IPL mowed the vegetation on the downstream slopes just prior to the inspection. There was no visible damage to the slopes by the mowing operations.

The following observations are noted.



Ash Ponds A, B, and C

The layouts of the Ponds A, B, and C are shown on **Figure 1**. At the time of the inspection, IPL was not operating the Eagle Valley Plant. Photographs taken during the inspection of Ponds A, B, and C are presented in **Attachment B** to this letter.

Results of the visual inspection performed on November 10, 2015, for Ponds A, B, and C is summarized below.

- The freeboard in Pond A appeared to remain adequate. The airspace previously provided was essentially full at this inspection.
- There was no discharge occurring from any of the ponds at the time of the inspection.
- The vegetation on all exterior slopes appeared to be in good condition. These slopes were mowed just prior to the inspection. The slopes appeared to be in good condition.
- The interior slopes of Pond C at the time of the inspection continued to appear to be in good condition. Pond C contained no evidence of water at the time of the inspection.
- The exterior slopes of Ponds A, B, and C continue to appear stable and well-vegetated with no visual evidence of seepage along the dike toes at the time of the inspection.
- The visible portions of the inside slope of the exterior dikes of Ponds A, B, and C continued to appear in good condition.
- There were no areas of softening or rutting noted during this inspection.
- IPL previously placed the material excavated from the interior of Pond A along the downstream slope of the intermediate dike between Pond A and Pond B as shown on **Figure 1**. No instabilities of the berm material were observed during placement, and the completed berm appeared stable during the inspection.

CONCLUSIONS AND RECOMMENDATIONS

Based on the observations made during the inspection, we conclude that conditions in Ponds A, B, and C are satisfactory at this time, and these basins show no visible signs of significant erosion or instability.

Recommendations for Ash Ponds A, B, and C

We make the following recommendations for Ponds A, B, and C.

1. Recommend that all interior slopes of perimeter dikes for Ponds A, B, and C be continued to be monitored for erosion and that rip-rap be placed on the interior slopes if and when erosion activities are significant.
2. Recommend that IPL continue systematic observation for all of the ash pond dikes with specific attention to the conditions in the rutted area on the downstream slope of the northeast corner of Pond A, noted in previous inspections. If conditions appear to change, IPL should contact Mr. Hendron as soon as practical to identify the need for response to the changes being observed.

SCS appreciates the opportunity to perform this inspection and looks forward to assisting IPL in future inspection of their ash disposal facilities. If you have any questions with regard to this report, please do not hesitate to contact me at 312-286-9397.

Sincerely,



David M. Hendron, PE
Indiana PE 10000050
SCS ENGINEERS

DH/AJV

Enclosures: Figure 1 – Location Plan of Basin and Ponds
Attachment A – IPL Dike Field Review Checklist Form
Attachment B – Photographs

FIGURE 1

Location Plan of Basin and Ponds



Figure 1 – Location Plan of Basin and Ponds

ATTACHMENT A

IPL Dike Field Review Checklist Form

IPL Dike Field Review Checklist – Inspection 15-2 – Eagle Valley Station

- 1) Complete all Portions of this Section (Pre-review) – Inspection 15-2
Date of Review: November 10, 2015
Name of Dike: Eagle Valley Basins A, B, and C Project Number: 25211357.31
- 2) Review Inventory – Highlight missing information (Pre-review)
Owner(s) Name(s): Indianapolis Power and Light Company (IPL)
Address: 4040 Blue Bluff Road
City: Martinsville State: Indiana Zip (+4) 46151-7887
Telephone (Home): _____ Telephone (Work): 765-349-3401
Contact Persons: Mr. Rick Jacobs and Mr. John Terrell
Designed By: IPL
Constructed By: IPL contractors and sub-contractors
Year Completed: Unknown Plans Available (Yes, No) (Location): Not complete for all ponds.
Purpose of Dike: Form basins for Ash Ponds A, B, and C at the Eagle Valley Facility
Age of Dike: _____
- 3) General Information
Mowing (times per year): Once or twice
Prior problems (wet areas, erosion, slides): See previous inspection reports.
Repair or modification (what & when): IPL has continued to make periodic monitoring and inspection of the dikes since last inspection. IPL continues to operate the EV plant on an intermittent basis and will not require full-time use of Ponds A through C for ash processing for the foreseeable future. Water levels in Ponds A, B, and C were significantly below the invert levels of discharge pipes in the ponds. There was no discharge from Pond C at the time of the inspection.
Failure/Incident/Breach (max. pool): None since the last inspection.
Downstream hazard status (recent changes): No changes

Dike Embankment Material: Primarily ash materials with well-vegetated downstream slope erosion protection. Vegetation in good condition as a result of recent rainfall amounts. Downstream slopes recently mowed.

Slope Erosion Control: Interior – rip-rap along most slopes. Only remaining interior slopes without rip-rap protection in the west and north of Pond C. Continue to recommend placing rip-rap in this area if erosion of the slopes is observed to occur. No significant erosion at the time of the inspection.
- 4) Field Information (while at site)
Pool Elevation (during review): Water level in all active Ponds were significantly below the discharge inverts for the ponds. Water level in Ponds B and C remain significantly below the invert of control structures.
Site Conditions (temp., weather, ground moisture): Clear and cool
Review Party: Dave Hendron, PE, and Mr. John Terrel. Mr. Terrel briefed after the inspection with a summary of findings.

5) INSIDE SLOPE

Gradient: Horizontal: Unknown

Vertical: (est. meas.)

Required
Action

None
Monitor
Maintenance
Engineer

☒ VEGETATION [no problem]

☒ Trees: Quantity: (<5, sparse, dense) None

Diameter: (<6", 6-12", >12")

Location:

Notes:

☒ ☐ ☐ ☐

☒ Brush: Quantity: (sparse, dense) None to sparse

Location: See photos

Notes:

☐ ☐ ☐ ☐

☒ Ground Cover: Type: (grass, crown vetch) Other:

quantity: (bare, sparse, adequate, dense) Poor where rip-rap not present in Pond C.

Appearance: (too tall, too short, good) Lush

Notes: Continue to monitor Pond C and add rip-rap if erosion is observed, and if Pond C water level is increased to impinge on exterior slope.

☐ ☒ ☐ ☐

☒ SLOPE PROTECTION [no problem, could not inspect thoroughly]

☐ None

☒ Riprap: Average Diameter: Approximately 5 to 6 inches where present.

(adequate, sparse, displaced, weathered, vegetation) (bedding/fabric noted=yes, no)

Notes: Rip-rap placed in most areas except for west and north interior slope of Pond C. Continue to recommend that rip-rap be placed as recommended in the previous section of this report.

☐ ☒ ☐ ☐

☐ Wave Berm:

Vegetation: (adequate, bare, sparse, improper vegetation)

Notes:

☐ ☐ ☐ ☐

☐ Other:

Notes:

☒ EROSION [no problem, could not inspect thoroughly]

☒ Wave Erosion (beaching): Scarp: Length: Height:

Location: Minor erosion noted on west and north interior slopes of Pond C.

Notes: Recommend to place rip-rap in these areas if erosion continues or if the water level in the basin impinges on exterior slope and erosion is observed.

☐ ☒ ☐ ☐

☒ Runoff Erosion (Gullies): Quantity: Some minor erosion noted on interior slopes of Pond C as noted previously in this inspection report.

Depth: Width:

Length:

Location:

Notes/Causes:

☐ ☒ ☐ ☐

☒ INSTABILITIES [no problem, could not inspect thoroughly]

☐ Slides: Transverse Length: Longitudinal Length:

Scarp: Width: Length:

Location:

Crack: Width: Depth:

Notes/Causes:

☒ ☐ ☐ ☐

☐ Cracks: ☐ Transverse ☐ Longitudinal ☐ Other

Quantity: Length: Width: Depth:

Location:

Notes/Causes:

{Inside Slope, Crest, Outside Slope, Outlet/Inlet Structures, Pond Drain}

☐ ☐ ☐ ☐

None
Monitor
Maintenance
Engineer

Required
Action

☐ Cracks: ☐ Transverse ☐ Longitudinal ☐ Other
 Quantity: _____ Length: _____ Width: _____ Depth: _____
 Location: _____
 Notes/Causes: _____

☐ ☐ ☐ ☐

☐ Bulges ☐ Depressions ☐ Hummocky
 Size: _____ Height: _____ Depth: _____
 Location: _____
 Notes/Causes: _____

☐ ☐ ☐ ☐

☐ Bulges ☐ Depressions ☐ Hummocky
 Size: _____ Height: _____ Depth: _____
 Location: _____
 Notes/Causes: _____

☒ **OTHER** [no problem, could not inspect thoroughly]

☐ Rodent Burrows: (few, numerous) **No animal activity noted.**
 Location: _____
 Notes/Causes: _____

☒ ☐ ☐ ☐

☐ Other: _____
 Notes: _____

☐ ☐ ☐ ☐

6) CREST Length: _____ Width: _____ (est. meas.)

☒ **VEGETATION** [no problem]

☐ Trees: Quantity: (<5, sparse, dense) _____
 Diameter: (<6", 6-12", >12") _____
 Location: _____
 Notes: _____

☒ ☐ ☐ ☐

☐ Brush: Quantity: (sparse, dense) _____
 Location: _____
 Notes: _____

☐ ☐ ☐ ☐

☐ Ground Cover: Type: (grass, crown vetch) Other: **Stone roadway continues in good condition in all areas of the ash ponds.**

☒ ☐ ☐ ☐

Quantity: (bare, sparse, adequate, dense) _____
 Appearance: (too tall, too short, good) _____
 Notes: _____

☒ **EROSION** [no problem, could not inspect thoroughly]

☐ Runoff Erosion (Gullies): Quantity: _____ Depth: _____ Width: _____ Length: _____
 Location: _____
 Notes: _____

☒ ☐ ☐ ☐

x ☐ **WIDTH [no problem]**

- ☐ Too Narrow

Location: _____

Notes/Causes: _____

x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>			

x ☐ **INSTABILITIES [no problem, could not inspect thoroughly]**

- ☐ Cracks: ☐ Transverse ☐ Longitudinal ☐ Other

Quantity: _____ Length: _____ Width: _____ Depth: _____

Location: _____

Notes/Causes: _____

x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-----------------------------------	--------------------------	--------------------------	--------------------------

- ☐ Cracks: ☐ Transverse ☐ Longitudinal ☐ Other

Quantity: _____ Length: _____ Width: _____ Depth: _____

Location: _____

Notes/Causes: _____

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

- ☐ Bulges: ☐ Depressions ☐ Hummocky

Size: _____ Height: _____ Depth: _____

Location: _____

Notes/Causes: _____

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

X ☐ **OTHER [no problem, could not inspect thoroughly]**

- ☐ Rodent Burrows: (few, numerous) _____

Location: _____

Notes: _____

x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-----------------------------------	--------------------------	--------------------------	--------------------------

X ☐ Other: Limited freeboard on the Eastern perimeter slope of Pond A has been corrected by excavation of an area of Pond A. Area appears to conform to previous recommendations. Pond A is not being used for ash processing at the time of inspection.

Notes: _____

<input type="checkbox"/>	<input type="checkbox"/>	x <input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	-----------------------------------	--------------------------

7) OUTSIDE SLOPE

Gradient: Horizontal: **3.0**

Vertical: **1.0**

(est. meas.)

x ☐ **VEGETATION [no problem]**

- ☐ Trees: Quantity: (<5, sparse, dense) _____

Diameter: (<6", 6-12", >12") _____

Location: _____

Notes: _____

x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-----------------------------------	--------------------------	--------------------------	--------------------------

- ☐ Brush: Quantity: (sparse, dense) _____

Location: _____

Notes: _____

x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-----------------------------------	--------------------------	--------------------------	--------------------------

- ☐ Ground Cover: Type: (**grass**, crown vetch) Other: _____

Quantity: (bare, sparse, adequate, **dense**) _____

Appearance: (too tall, too short, **good**) _____

Notes: **Vegetation was mowed just prior to the inspection. Vegetation appeared to be in good condition throughout.**

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

{Inside Slope, Crest, **Outside Slope**, Outlet/Inlet Structures, Pond Drain}

x ☐ **EROSION** [no problem, could not inspect thoroughly]

☐ Runoff Erosion (Gullies): Quantity: _____ Depth: _____ Width: _____ Length: _____

Location: _____

Notes/Causes: _____

x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-----------------------------------	--------------------------	--------------------------	--------------------------

x ☐ **INSTABILITIES** [no problem, could not inspect thoroughly]

☐ Slides: Transverse Length: _____ Longitudinal Length: _____

Scarp: Width: _____ Length: _____

Location: _____

Crack: Width: _____ Length: _____

Notes/Causes: _____

x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-----------------------------------	--------------------------	--------------------------	--------------------------

☐ Cracks: ☐ Transverse ☐ Longitudinal ☐ Other

Quantity: _____ Length: _____ Width: _____ Depth: _____

Location: _____

Notes/Causes: _____

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

☐ Cracks: ☐ Transverse ☐ Longitudinal ☐ Other

Quantity: _____ Length: _____ Width: _____ Depth: _____

Location: _____

Notes/Causes: _____

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

☐ Bulges: ☐ Depressions **x** ☐ Hummocky

Size: _____ Height: _____ Depth: _____

Location: _____

Notes/Causes: **No evidence of new rutting or seepage on any exterior slope during this inspection.**

<input type="checkbox"/>	x <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	-----------------------------------	--------------------------	--------------------------

x ☐ **OTHER** [no problem, could not inspect thoroughly]

☐ Rodent Burrows: (few, numerous) **None observed**

☐ Other: _____

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

x ☐ **SEEPAGE** [no problem, could not inspect thoroughly]

☐ Wet Area ☐ Flow ☐ Boil ☐ Sinkhole

Flow Rate: _____

Location: _____ ☐ Aquatic Vegetation

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

Size:

☐ None

☐ Rust Colored Deposits ☐ None

☐ Sediment in Flow **x** ☐ None

☐ Other: _____

Notes/Causes: _____

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

Required Action

{Inside Slope, Crest, **Outside Slope**, Outlet/Inlet Structures, Pond Drain}

None	Monitor	Maintenance	Engineer
------	---------	-------------	----------

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------

☐ Wet Area ☐ Flow ☐ Boil ☐ Sinkhole
 Flow Rate _____ Size: _____
 Location: _____
☐ Aquatic Vegetation ☐ None
☐ Rust Colored Deposits ☐ None
☐ Sediment in Flow ☐ None
☐ Other: _____
 Notes/Causes: _____

8) OUTLET/INLET STRUCTURES

x ☒ **GENERAL INLET** [no problem, could not inspect thoroughly]

☒ Inlet Pipe Dimensions: **About 10 inches** (adequate, too small)
 Type: (steel, concrete, aluminum, stainless steel, corrugated metal wood, other): **Steel**
 Location: _____
 Deterioration: (missing sections, rusted, collapsed) _____
 In Use: (Yes, **No**)
☒ Pond Erosion at Inlet: (Describe) **None observed**
☐ Other – _____

x ☒ **OUTLET STRUCTURES** [no problem, could not inspect thoroughly]

☐ Number of Outlet Structures: **Three**
☒ Description/Location of Outlet Structures: **All outlet structures visible at the time of the inspection. All appeared to be in good condition. Water level in ash Ponds A, B, and C was below the invert elevation of all discharge pipes. No discharge was occurring from Pond C at the time of the inspection.**

☒ Outlet Structure 1: **Basin A to Basin B**
 Type: (steel, concrete, aluminum, stainless steel, corrugated metal wood, other): _____
 Deterioration: (missing section, collapsed, rusted): _____
 Erosion at Outlet Structure: (soil piping, seep collar, etc.) _____
 Debris: (leaves, trash, logs, ice, etc.) _____
 Notes: **No discharge occurring at the time of the inspection.**

{Inside Slope, Crest, Outside Slope, **Outlet/Inlet Structures**, Pond Drain}

☒ Outlet Structure 2 **Basin B to Basin C**

Type: (steel, concrete, aluminum, stainless steel, corrugated metal wood, other): _____

☒ ☐ ☐ ☐

Deterioration:(missing section, collapsed, rusted): _____

Erosion at Outlet Structure: (soil piping, seep collar, etc.) _____

Debris: (leaves, trash, logs, ice, etc.) _____

Notes: **No discharge at the time of the inspection.**

☒ Outlet Structure 3 **Basin C to the river**

Type: (steel, concrete, aluminum, stainless steel, corrugated metal wood, other): _____

☒ ☐ ☐ ☐

Deterioration:(missing section, collapsed, rusted): _____

Erosion at Outlet Structure: (soil piping, seep collar, etc.) _____

Debris: (leaves, trash, logs, ice, etc.) _____

Notes: **No discharge occurring at the time of the inspection.**

☒ Outlet Structure 4

Type: (steel, concrete, aluminum, stainless steel, corrugated metal wood, other): _____

Deterioration:(missing section, collapsed, rusted): _____

Erosion at Outlet Structure: (soil piping, seep collar, etc.) _____

Debris: (leaves, trash, logs, ice, etc.) _____

☐ ☐ ☐ ☐
☐ ☐ ☐ ☐

Notes:

9) **POND DRAIN**

☒ **GENERAL**

☐ ☐ ☐ ☐

☐ None Found ☐ Does not have one

☒ Type of Pond Drain **Drainage provided by Outlet 3 to the river**

(isolated control/intake tower, valve vault w/outlet conduit, valve in riser/drop inlet, siphon)

☒ ☐ ☐ ☐

Notes: _____

☐ Operated During Inspection (yes, **no**)

Notes: _____

☒ **ACCESS TO VALVE/SLUICE GATE** [no problem, could not inspect thoroughly]

☒ ☐ ☐ ☐

☒ Type (not accessible, from shore, boat, **walkway**, other) _____

Notes _____

☐ Walkway/Platform: _____

☐ Concrete Deterioration ☐ Cracks (platform, piers, end supports, railing)

Location: **Northwest corner of Pond C**

Notes: **Appeared to be In satisfactory condition. Valve operation not tested.**

{Inside Slope, Crest, Outside Slope, Outlet/Inlet Structures, **Pond Drain**}

		Required Action			
		None	Monitor	Maintenance	Engineer
<input type="checkbox"/>	Wood Deterioration Notes: _____ _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	Metal Deterioration (minor, moderate, extensive, other) Notes: _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
x	POND DRAIN COMPONENTS [no problem, could not inspect thoroughly]				
X	Concrete Structure Locations: _____ Description: (deterioration, misalignment, cracks): _____ Notes/Causes: _____ _____	X	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
X	Valve Control (Operating Device) <input type="checkbox"/> No Operating Device <input type="checkbox"/> No Stem <input type="checkbox"/> Bent/Broken Stem <input type="checkbox"/> Other Notes/Operability: Not tested at this inspection	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	Metal Deterioration: (surface rust, minor, moderate, extensive, other) Location: _____ Flow Rate: _____ Notes/Causes: _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	Mis-alignment Notes/Causes: _____ _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	Leakage – Flow Rate: Notes/Causes: _____ _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	Outlet Conduit				
<input type="checkbox"/>	Metal: (loss of coating/paint, surface rust, corrosion (pitting, scaling), rusted out) Location: _____ Notes/Causes: _____ _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	Concrete (bug holes, hairline crack, efflorescence) (spalling, popouts, honeycombing, scaling, craze/map cracks) (isolated crack, exposed rebar, disintegration, other) Dimensions/Location: _____ Notes/Causes: _____ _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	Plastic: (deterioration, cracking) _____ Location: _____ Notes/Causes: _____ _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<div style="display: flex; justify-content: space-between; align-items: flex-end;"> {Inside Slope, Crest, Outside Slope, Outlet/Inlet Structures, Pond Drain} <div style="text-align: right;"> <div>None Monitor Maintenance Engineer</div> <div>Required Action</div> </div> </div>					

		Required Action			
		None	Monitor	Maintenance	Engineer
<input type="checkbox"/> Conduit Deformation	<input type="checkbox"/> Mis-Alignment:				
Location: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes/Causes: _____					

<input type="checkbox"/> Separated Joint	<input type="checkbox"/> Loss of Joint Material				
Location/Description: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes/Causes: _____					

<input type="checkbox"/> Undermining					
Location/Description: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes/Causes: _____					

<input type="checkbox"/> Vegetation (trees, brush)					
Notes: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

<input type="checkbox"/> Other					
Notes: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

<input type="checkbox"/> Discharge Outlet					
<input type="checkbox"/> Type (pipe outlet, concrete channel, rock-lined channel, none)		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes: _____					

<input type="checkbox"/> Riprap: Average Diameter:					
(adequate, sparse, displaced, weathered, vegetation) bedding/fabric noted – yes, no))		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes: _____					

<input type="checkbox"/> Concrete (bug holes, hairline crack, efflorescence)					
(spalling, popouts, honeycombing, scaling, craze/map cracks)		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
(isolated crack, exposed rebar, disintegration, other)					
Dimensions/Location: _____					
Notes/Causes: _____					

<input type="checkbox"/> Mis-alignment					
Location/Description: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes/Causes: _____					

<input type="checkbox"/> Separated Joint	<input type="checkbox"/> Loss of Joint Material				
Location/Description: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes/Causes: _____					

<input type="checkbox"/> Undermining					
Location/Description: _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Notes/Causes: _____					

<input type="checkbox"/> Other					
Notes: _____					

{Inside Slope, Crest, Outside Slope, Outlet/Inlet Structures, Pond Drain }					

ATTACHMENT B

Photographs

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 1: Pond A, looking west from the Northeast corner of Pond A.



Photo 2: Same, looking southwest.



Photo 3: Same, looking south.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 4: Typical condition of the downstream slope of the East perimeter dike of Pond A.



Photo 5: Freeboard in the Northeast corner of Pond A.



Photo 6: Surface of Pond A, looking southeast from the center of the East perimeter dike of Pond A.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 7: Same, looking south.



Photo 8: Pond A, looking north from the Southeast corner of Pond A.



Photo 9: Same, looking west.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 10: Typical condition of the downstream slope of the East perimeter dike of Pond A, looking north from the Southeast corner of Pond A.



Photo 11: Typical conditions of the downstream slope of the South perimeter dike of Pond A, looking west.



Photo 12: Typical condition of the crest and downstream slope of the West perimeter dike of Pond A and Pond B, looking north from the Southwest corner of Pond B.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 13: Outlet from Pond A to Pond B.



Photo 14: Discharge pipes from Pond A into Pond B. No discharge at the time of the inspection.



Photo 15: Downstream slope of intermediate dike between Pond A and Pond B, looking northeast from West end of intermediate dike.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 16: Typical condition of the interior slope of the West perimeter dike of Pond B, looking north from the West end of the intermediate dike.



Photo 17: Same as Photo 16, looking northeast from the center of the intermediate dike.



Photo 18: Pond B, looking east from the Northwest corner of Pond B.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 19: Same, looking south.



Photo 20: Same, looking at the condition of the rip-rap placed in the Northwest corner of Pond B.



Photo 21: Outlet from Pond B into Pond C.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 22: Outlet from Pond B into Pond C. No discharge occurring at the time of the inspection.



Photo 23: Typical condition of the downstream slope of Pond B, looking south from the Northwest corner of Pond B.



Photo 24: Same, looking north.

**IPL Eagle Valley Station – Ponds A-C – 15-2 Inspection
Martinsville, Indiana
SCS Engineers Project #25211357.31**



Photo 25: Outlet structure and interior slope of the West perimeter dike of Pond C, looking south from the Northwest corner of Pond C.