FORM D.2

Ash Pond System – Annual EAP Participant Meeting Log (Page 1 of 2)

NAME	TITLE	COMPANY/ODCANIZATION
In accordance with 40 CFR 257.73(a)(i)(organization and local emergency responsible Street Generating Station on the preceding	ders was completed via ema	ail/phone discussions at the Harding
Date of Meeting:11/1/2019 Annua	al EAP Review	
Name of Dike: Harding Street Generating	g Station - Ash Pond Systen	n

NAME	TITLE	COMPANY/ORGANIZATION
Dennis Peters	Administrator	IMPD Homeland Security Bureau – Emergency Management Agency
Thom O'Leary	Senior Environmental Specialist	Management Agency IPL – ECCP Group

FORM D.2

Ash Pond System – Annual EAP Participant Meeting Log (Page 2 of 2)

Name of Dike: Harding Street Generating Station - Ash Pond System			
Date of Meeting: 11/1/2019 Annual EAP Review			
In accordance with 40 CFR 257.73(a)(i)(3)(E), the annual meeting between IPL's internal EAP organization and local emergency responders was completed via email/phone discussions at the Harding Street Generating Station on the preceding date. The following topics were discussed:			
ANNUAL EAP PARTICIPANT MEETING NOTES			
Discussed through emails and phone conversations the contents of the EAP. EAP originally sent to IMPD Homeland Security Bureau – Emergency Management Agency for review on 11/1/2019 with follow-up discussion/emails on 11/4/2019. Made minor clarifications to the EAP based on the review and discussions. Noted that ash has not been sluiced to the ash ponds since 2/2016 when the facility converted to gas. Noted, with the exception of pond 3, that all ash ponds have been dry since early 2018.			