



**FORM D.2**

Ash Pond System – Annual EAP Participant Meeting Log  
(Page 2 of 2)

Name of Dike: Harding Street Generating Station - Ash Pond System

Date of Meeting: 11/13/20 Annual EAP Review. 1/7/21 site tour.

In accordance with 40 CFR 257.73(a)(i)(3)(E), the annual meeting between IPL’s internal EAP organization and local emergency responders was completed via email and a site tour at the Harding Street Generating Station on the preceding dates. The following topics were discussed:

**ANNUAL EAP PARTICIPANT MEETING NOTES**

EAP sent to IMPD Homeland Security Bureau – Emergency Management Agency for review on 11/13/2020 with a site tour conducted on 1/7/2021.  
No revisions were required to the EAP based on the review and site tour.  
Noted that ash has not been sluiced to the ash ponds since 2/2016 when the facility converted to gas.  
Observed that, with the exception of pond 3, all ash ponds have been dry since early 2018. There was deminimus water present in pond 3.