

FORM D.2

Ash Pond System – Annual EAP Participant Meeting Log
(Page 2 of 2)

Name of Dike: Harding Street Generating Station - Ash Pond System

Date of Meeting: 12/2/21 Annual EAP Review.

In accordance with 40 CFR 257.73(a)(i)(3)(E), the annual meeting/review between AES Indiana’s (formerly IPL) internal EAP organization and local emergency responders was completed via email for the Harding Street Generating Station on the preceding date. The following topics were discussed:

ANNUAL EAP PARTICIPANT MEETING NOTES

Discussed through emails the contents of the EAP. The EAP had been sent to IMPD Homeland Security Bureau – Emergency Management Agency for review on 10/8/2021. Email correspondence on 12/2/21 did not indicate that a site visit was necessary as there have been no changes to the EAP or site conditions. No revisions were required to the EAP based on the review.

Noted that ash has not been sluiced to the ash ponds since 2/2016 when the facility converted to gas. With the exception of pond 3, all ash ponds have been dry since early 2018. There was deminimus water present in pond 3.